CALTIRE

INVOICE

Invoice #: 045498461 Order Date: Oct 01 2024 Completed Date: Oct 03 2024

Page: 1

Team Member: BRMACDONAL

3,2024

Purchase

Oct 03, 2024 16:57:26 VISA ******0481 Invoice # 498461 TID: *****761 Entry: Chip (C) Sequence 300 032

Auth#: 018148 Response: 01-027

Batch 300

Total

\$ 302.37 Amount

\$ 302.37

A0000000031010 VISA CREDIT TVR 0080008000 TSI E800

Approved

Important Retain this copy for your record

Cardholder copy

GST/HST: 122644537

Year: 2007 Make: MAZDA

Model: 5 Unit: BLUE Lic #: KSS929 Prov: BC

VIN: JM10R1938J0145271

Mi/KM: 239861

Qty	Product Code	Description	Price	Unit	Amount
1	DIA	DIAGNOSE CUSTOMER CONCERN	79.33	EA	79.33
	BAD NOISE FROM	REAR SOUNDS LIKE TIRE IS FALLING OFF			
2	1041362	STRUT MOUNT - ULTRA-8	42.22	PCS	84.44
0.9	0 FES	SHOCK &/OR STRUT ASSEMBLY - R&I OR R&R	118.00	HR	106.20
	Both DOES NOT in	nclude disassemble or alignment. Rear			
1	TRQC	*YOUR WHEELS HAVE BEEN TORQUED	N/C	EA	N/C

I AM THE PERSON WHO REQUESTED THAT THE ABOVE WORK BE DONE AND MATERIAL SUPPLIED, OR I AM THE AUTHORIZED AGENT FOR THAT PERSON/COMPANY. I ACKNOWLEDGE INDEBTEDNESS FOR THE WORK DONE AND MATERIALS SUPPLIED IN THE AMOUNT OF \$302.37, BEING THE TOTAL AMOUNT OWING AS SHOWN HEREON, OR IN THE AMOUNT OF ANY CHEQUE OR CREDIT CARD GIVEN IN PAYMENT AND LATER DISHONOURED. TITLE TO THE GOODS DOES NOT TRANSFER UNTIL PAYMENT IS RECEIVED IN **FULL FOR SAID GOODS.**

Agreed Terms: CASH SALE Interest of 16% per Annum Payable on Overdue Accounts.

Subtotal	269.97
BC PST	18.90
BC GST/HST	13.50
Total	302.37
Visa	(302.37)
Balance	0.00

IF WE SELL IT... WE GUARANTEE IT! WE WELCOME YOUR COMMENTS! CALL US WEEKDAYS AT 8AM TO 5PM (PACIFIC TIME) AT 1-800-663-9350 OR EMAIL US AT CUSTOMERSERVICE@KALTIRE.COM

Signed	X	
Release	Date:	

Printed: Oct 03 2024 16:58

Driver: Phone: **THANK YOU FOR YOUR BUSINESS**

Page: 1 Invoice #: 045498461

Invoice-3.1.1

TRANSACTION RECORD
TRELAND
437 LEGION DRIVE
QUESNEL BC

Purchase

Sep 25,2024 16:58:48
VISA 17ID: V3710365
Sequence: 001 812
Auth#: 05459F
Response: 01-027

Batch: 001 \$ 326.86

Amount

Total \$ 326.86

A0000000031010 VISA CREDIT TVR 0080008000 TSI E800

SERIAL#

Approved

Important Retain this copy for your record

Cardholder copy

ELAMD)

AUTO CENTRE

1 Minute Muffler Ltd

437 Legion Drive Quesnel, B.C. V2J 2A5

Ph: (250) 992-6502

GST# 10579 9670 RT0001

Sept 25,

Page 1

Sale Time: 16:46

Account #: 1

Invoice:# 168978 Date: 25/09/2024

Sales Per: AMY2220

Paid.by: CR/CD

Lic-Unit Kilometers/Hours Model
MD779N 239634 TRAILING ARM BUSHING MAZDA 5

Item-Number	Qty	Description	List	Sell	lotal
K200064	1.00	TRAILING ARM BUSHING	95.10	85.59	85.59
LABOUR	1.50	LABOUR, MECHANICAL	125.00	125.00	187.50
SUP	1.00	SUPPLIES & DISPOSAL	18.75	18.75	18.75

SIGNATURE: _____

Trust the Pros! www.tireland.ca Sub-Total: 291.84
Pst-Tax: 20.43
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF: Total: 326.86

Note: If the wheels have been removed, they have been torqued to manufacturers specifications and must be re-torqued within 100 kms.

This is the clients responsibility. Failure to re-torque the wheels may result in damage to the vehicle. Any damages resulting from a loose wheel are the responsibility of the vehicle operator. You may return to 1 Minute Muffler/Tireland and have the wheels re-torqued at no charge to you.

Conditions: If the above total charge is not paid in full, the owner authorizes this company to repossess the vehicle and hold it until the bill is paid or to sell it.

Warranty: 90 days on all parts and labour. One year on exhaust parts.

TRANSACTION RECORD ---KAL-TIRE #665 1949 CARIBOO HWY 97 N QUESNEL BC

Purchase

Sep 24,2024 12 43 57 ***********7041 665239681 Invoice # TID *****382 Entry Chip (C) Sequence 17 | 006

Auth# 00729F Response: 01-027

A0000000031010 VISA CREDIT TVR 0080008000 TSI E800

Batch 171

Amount

Total

\$ 184.73

\$ 184.73

GST/HST: 122644537

Approved

Important Retain this copy for your record

Cardholder copy

Year: 2009 Make: MAZDA

Model: 5 Unit: Lic #: Prov:

VIN: JM1CR293790330193

Mi/KM: 239601

Product Code Description Price Unit Amount **PSS** PASSENGER TIRE - SEASONAL SWAP 14.00 EA 56.00 1 ALT LIGHT TRUCK SET TOE ONLY 108.93 EA 108.93 TRQC ***YOUR WHEELS HAVE BEEN TORQUED** N/C EA N/C **FSN FUTURE SERVICE NOTES** N/C EA N/C front end adjust only rear adjusment null, trailing arm bushing gone. ----- Notes -----

something clunking right rear

I AM THE PERSON WHO REQUESTED THAT THE ABOVE WORK BE DONE AND MATERIAL SUPPLIED, OR I AM THE AUTHORIZED AGENT FOR THAT PERSON/COMPANY. I ACKNOWLEDGE INDEBTEDNESS FOR THE WORK DONE AND MATERIALS SUPPLIED IN THE AMOUNT OF \$184.73, BEING THE TOTAL AMOUNT OWING AS SHOWN HEREON, OR IN THE AMOUNT OF ANY CHEQUE OR CREDIT CARD GIVEN IN PAYMENT AND LATER DISHONOURED. TITLE TO THE GOODS DOES NOT TRANSFER UNTIL PAYMENT IS RECEIVED IN **FULL FOR SAID GOODS.**

Agreed Terms: CASH SALE

Interest of 16% per Annum Payable on Overdue Accounts.

Subtotal	164.93
BC PST	
BC GST/HST	11.55 8.25
Total	6.25 184.73
Visa	(184.73)
Balance	0.00

IF WE SELL IT... WE GUARANTEE IT! WE WELCOME YOUR COMMENTS! CALL US WEEKDAYS AT 8AM TO 5PM (PACIFIC TIME) AT 1-800-663-9350 OR EMAIL US AT CUSTOMERSERVICE@KALTIRE.COM

Signed	<u>X</u>		
Release	Date:		

Printed: Sep 24 2024 12:44

Driver: Phone:

THANK YOU FOR YOUR BUSINESS

Page: 1 Invoice #: 665239681

Invoice-3.1.1

5ept 24

Invoice #: 665239681 Order Date: Sep 24 2024

Completed Date: Sep 24 2024 Page: 1

Team Member: MHOLMAN

INVOICE

TRANSACTION RECORDTIRELAND

437 LEGION DRIVE
OUESNEL BC

TID: 19010419

Entry Chip (C)

Sequence 001 859 Auth#: 03653Z

Response. 01-027

Batch: 001

\$ 799.64

Total

Amount

\$ 799.64

A0000000041010 Tangerine Card TVR 0000008000 TSI E800

Approved

Important Retain this copy for your record

Cardholder copy

AUTO CENTRE

1 Minute Muffler Ltd

437 Legion Drive Quesnel, B.C. V2J 2A5

Ph: (250) 992-6502

GST# 10579 9670 RT0001

Jan 18/2024

Page 1

Sale Time: 15:50 Account #: 1 Invoice:# 165035 Date: 18/01/2024

Sales Per: AMY2220

Paid.by: CR/CD

Irs Model
LOWER CONTROL ARM MAZDA 5

SERIAL #	'				
Item-Number	Qty	Description	List	Sell	Total
RK620040	1.00	RIGHT LOWER CONTROL ARM	222.54	200.29	200.29
RK620041	1.00	LEFT LOWER CONTROL ARM	222.54	200.29	200.29
LABOUR	2.50	LABOUR, MECHANICAL	115.00	115.00	287.50
SUP	1.00	SUPPLIES & DISPOSAL	25.88	25.88	25.88

SIGNATURE:

Trust the Pros! www.tireland.ca Sub-Total: 713.96
Pst-Tax: 49.98
Gst-Tax: 35.70
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF: Total: 799.64

Note: If the wheels have been removed, they have been torqued to manufacturers specifications and must be re-torqued within 100 kms.

This is the clients responsibility. Failure to re-torque the wheels may result in damage to the vehicle. Any damages resulting from a loose wheel are the responsibility of the vehicle operator. You may return to 1 Minute Muffler/Tireland and have the wheels re-torqued at no charge to you.

Conditions: If the above total charge is not paid in full, the owner authorizes this company to repossess the vehicle and hold it until the bill is paid or to sell it.

Warranty: 90 days on all parts and labour. One year on exhaust parts.

SIMOES AUTOMOTIVE LTD 454 BETA ST VICTORIA BC V8Z 1B1 250-995-2434

DEBIT SALE

Batch #: 935 %

REF#: 00000007

RRN: 991569520927

victoria, BC. V8Z1B1 Phone: 250-995-2434 Fax: 000-Org. Est. # 061238

Printed Date: 09/27/2023

Work Completed: 09/27/2023

2009 Mazda - 5 Sport - 2.3L, In-Line4 (138CI) VIN(3)

Lic #: MD7 79N

Odometer In: 214918

Batch #: 935 RRN: 99 5655255					
APPR CODE: 554940				VIN #: JM1CR2937 90330193	
Trace: 7 DEBIT/CHEQUING Chip	Qty	Sale	Ext	Labor Description	Ext
***********4009	1.00	10.76	10.76	LUBE OIL FILTER CHANGE OIL AND VEHICLE CHECK OVER	39.95
AMOUNT \$215.33	4.30	6.95	29.89	RIGHT FRONT HEADLIGHT OUT REPLACE HEADLIGHT BULB	47.25
Interac	3.00	1.95	5.85	REPLACE HEADLIGHT SOCKET 645-540 ***********************************	n/c
AID: A0000002771010 TVR: 00 80 00 80 00 TSt: E8 00	1.00	18.26	18.26	REAR BRAKES 5 MM	
THANK YOU / MERCI	1.00	26.38	26.38	BATTERY TESTS WEAK P/STEERING FLUID GETTING DIRTY ALL FOUR TIRES MARGINAL - GETTING LOV	V
CUSTOMER COPY			8.92	FRONT CONTROL ARMS POOR Environmental Charge	
				Charge	5.00
				Taxes	
				PST	13.46
				GST	9.61

Org. Estimate 215.33 Revisions 0.00 **Current Estimate** 215.33

Labor: 87.20 Parts: 100.06 HazMat: 5.00

SubTotal:

192.26 23.07

Total:

Tax:

215.33

Bal Due:

\$0.00

Vehicle Received: 9/27/2023

[Payments - Debit Card - \$215.33]

Customer Number: 12675

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature

Date



1 Minute Muffler Ltd 437 Legion Drive Quesnel, B.C. V2J 2A5

Ph: (250)992-6502

GST# 10579 9670 RT0001

Sold To: 1ACASH

Feb 16/22

Page 1
Sale Time: 15:19
Account #: 1

Invoice:# 153044 Date: 16/02/2022 Sales Per: AMY2220

Invoice Pd.by: CR/CD

Lic-Unit Kilometers/Hours Model
MD779N 183083 REAR SHOCKS/SWARY BAR LI MAZDA 5
SERIAL #

Item-Number	Qty	Description	List	Sell	Total
5607	2.00	REAR SHOCKS	120.28	108.25	216.50
K80867	1.00	L/R SWAR BAR LINK	112.80	101.52	101.52
LABOUR SUP	1.50 1.00	LABOUR, MECHANICAL SUPPLIES & DISPOSAL	105.00 14.18	105.00 14.18	157.50 14.18

 SIGNATURE:
 Sub-Total:
 489.70

 Pst-Tax:
 34.28

 Gst-Tax:
 24.49

 Total:
 548.47

Trust the Pros!

www.tireland.ca

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF:

Note: If the wheels have been removed they have been torqued to manufacturers specifications and must be re-torqued within 100 km. This is the clients responsibility. Failure to re-torque the wheels may result in damage to the vehicle. Any damages resulting from a loose wheel are the responsibility of the vehicle operator. You may return to 1 Minute Muffler-Tireland and have the wheels re-torqued at no charge to you.

Conditions: If the above total charge is not paid in full the owner authorizes this company to repossess the vehicle and hold it until the bill is paid or to sell it. Warranty: 90 days on all parts and labour. One year on exhaust parts.