



HYUNDAI

SAFETY INSPECTION

CERTIFICATE



Make: HYUNDAI Model: IONIQ Year: 2019 Stock # H25700A

VIN # KMHAC85LH4K4041601 Original in Service Date _____

Date of Inspection MAR 19, 2025 R.O.# 68423 Odometer Reading 147439 KMS

Please circle the appropriate initial for each subject Y = Yes, N = No, G = Good P = Poor

ENGINE COMPRESSION TEST

Cyl #1 _____ Cyl #2 _____ Cyl #3 _____ Cyl #4 _____
Cyl #5 _____ Cyl #6 _____ Cyl #7 _____ Cyl #8 _____

ENGINE

	FAULT FOUND	REPAIR	REPLACE
Leaks	Y <u>(N)</u>	Y N	Y N
Running temperature	Y <u>(N)</u>	Y N	Y N
Oil consumption sign	Y <u>(N)</u>	Y N	Y N
Oil Pressure	Y <u>(N)</u>	Y N	Y N
Timing Belt Condition	Y <u>(N)</u>	Y N	Y N
Comments	_____		

SUSPENSION

Wheel Bearing	Y <u>(N)</u>	Y N	Y N
Ball Joints	Y <u>(N)</u>	Y N	Y N
Bushings	Y <u>(N)</u>	Y N	Y N
Comments	_____		

STEERING

	FAULT FOUND	REPAIR	REPLACE
Leaks	Y <u>(N)</u>	Y N	Y N
Loose Components	Y <u>(N)</u>	Y N	Y N
Comments	_____		

TRANSMISSION

	FAULT FOUND	REPAIR	REPLACE
Oil leak	Y <u>(N)</u>	Y N	Y N
CV Boots	Y <u>(N)</u>	Y N	Y N
<i>no tolerance on cracked cv boots</i>			
CV Joints	Y <u>(N)</u>	Y N	Y N
U-Joints	Y <u>(N)</u>	Y N	Y N
Comments	_____		

BRAKE SYSTEM

	FAULT FOUND	REPAIR	REPLACE
Hand Brake	Y <u>(N)</u>	Y N	Y N
Oil Leak	Y <u>(N)</u>	Y N	Y N
Hydraulic System	Y <u>(N)</u>	Y N	Y N
ABS	Y <u>(N)</u>	Y N	Y N
Comments	<u>FRONT BRAKE LF-8MM RF-8MM</u> <u>REAR BRAKES LR-7MM RR-7MM</u>		

AIR CONDITIONING

	FAULT FOUND	REPAIR	REPLACE
Noise	Y <u>(N)</u>	Y N	Y N
Operation	Y <u>(N)</u>	Y N	Y N
A/C Condensor	Y <u>(N)</u>	Y N	Y N
Comments	_____		

COOLING SYSTEM

	CONDITION	REPAIR	REPLACE
Radiator	<u>(G)</u> P	Y N	Y N
Coolant	<u>(G)</u> P	Y N	Y N
Water Pump	<u>(G)</u> P	Y N	Y N
Cooling Fan	<u>(G)</u> P	Y N	Y N
Sensors and Guages	<u>(G)</u> P	Y N	Y N
Comments	_____		

ROAD TEST AFTER INSPECTION

Any Vibration / Noises	<u>NO</u>
Engine Respond	<u>GOOD</u>
Transmission Respond	<u>GOOD</u>
A/C and Heating System	<u>GOOD</u>
Comments	_____

ELECTRICAL

	FAULT FOUND	REPAIR	REPLACE
Alternator	Y <u>(N)</u>	Y N	Y N
Starter	Y <u>(N)</u>	Y N	Y N
Cruis Contro	Y <u>(N)</u>	Y N	Y N
All elec. Motors	Y <u>(N)</u>	Y N	Y N
Ignition System (inc distributor)	Y <u>(N)</u>	Y N	Y N
Comments	_____		

Technician Name: GORDON

Service Manager: _____

Lougheed Hyundai

Dealer Code: 61062 Date: MAR 19, 25

Authorized Signature: [Signature]