

# Multi-Point Inspection Form

RO# 268960

VIN 1HGFA16326L808681

Advisor Cole Roman

Technician Ronald Requeno

Created On 12/30/2023

☒ Checked and OK at this time

☒ May Require Future Attention

☐ Requires immediate attention

## Interior / Exterior

- ☒ ☐ ☐ Bulbs and Lights
- ☐ ☒ ☐ Windshield Washer Spray / Wiper Operation / Wiper Blades / Including Rear (if applicable)
- ☒ ☐ ☐ Windshield / Window Condition
- ☒ ☐ ☐ Upholstery / Carpet / Floor Mats / Mirrors / Trim
- ☒ ☐ ☐ Emergency Brake Adjustment
- ☒ ☐ ☐ Horn Operation
- ☒ ☐ ☐ Fuel Tank Cap Gasket
- ☐ ☐ ☐ Clutch Operation (if equipped)
- ☒ ☐ ☐ Cabin/HEPA Filter (if equipped)

## Battery Performance

- ☒ ☐ ☐ Battery Terminals / Cables / Mountings
- ☒ ☐ ☐ Check Condition of Battery (Storage Capacity Test if Applicable)

## Under Hood

- ☐ ☒ ☐ Fluids: Oil / Coolant / Power Steering / Brake Fluid / Washer
- ☒ ☐ ☐ Engine Air Filter
- ☒ ☐ ☐ Belts / Tensioners (condition and adjustment)
- ☒ ☐ ☐ Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
- ☒ ☐ ☐ Radiator Core / Air Conditioning Condenser (if equipped)

## Under Vehicle

- ☒ ☐ ☐ Shock Absorbers / Suspension
- ☒ ☐ ☐ Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
- ☒ ☐ ☐ Muffler / Exhaust Pipes / Mountings
- ☒ ☐ ☐ Engine Oil and/or Fluid Leaks
- ☒ ☐ ☐ Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
- ☒ ☐ ☐ Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
- ☒ ☐ ☐ Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
- ☒ ☐ ☐ Inspect Nuts and Bolts on Body Chassis

## Tread Depth (measured in 1/32")



- ☐ ☐ ☒ LF 3
- ☐ ☐ ☒ RF 3
- ☒ ☐ ☐ LR 6
- ☒ ☐ ☐ RR 6
- ☐ ☐ ☐ Spare Tire (if applicable)
- ☒ ☐ ☐ LF/RF Tire Pressure 32
- ☒ ☐ ☐ LR/RR Tire Pressure 32

## Abnormal Wear Pattern of Tires

- ☐ ☒ ☐ LF
- ☐ ☒ ☐ RF
- ☒ ☐ ☐ LR
- ☒ ☐ ☐ RR

## Check Brake Linings Visual Inspection

- ☒ ☐ ☐ LF 8
- ☒ ☐ ☐ RF 8
- ☒ ☐ ☐ LR DRUM
- ☒ ☐ ☐ RR DRUM